




MIS	L	D	SW
6X10	70	22	19
6X14	70,5	22	19
8X12	70	22	19
8X14	70,5	22	19
8X17	70,5	22	19
10X15	70,5	22	19

ART. 727 PRESA RAPIDA CON PORTAGOMMA

Temperatura di esercizio: -15°C- + 80°C

Pressione: 0-16 bar