

C	D	E	Conf.	Inb.	A	B	
16	8	14x70	8	16	100	20	32
20	10	14x70	111/10/25	12	100	25	32
16	8	14x70	8	8	120	20	32
20	10	14x70	6	12	120	25	32
20	10	14x70	4	4	120	32	44
16	8	14x70	8	8	140	20	32
20	10	14x70	6	6	140	25	32
20	10	16x70	4	4	140	32	44
16	8	14x70	8	8	160	20	32
20	10	14x70	6	6	160	25	32
20	10	16x70	4	4	160	32	44
20	10	16x70	2	2	200	32	44
20	10	18x90	2	2	250	32	44
9	6	10x45	20	40	50	17	19
9	6	10x45	14	28	60	17	19
9	6	10x45	14	28	70	17	19
16	8	14x70	12	24	70	20	32
9	6	10x45	14	28	80	17	19
16	8	14x70	111/8/20	10	80	20	111/8/20
20	10	14x70	8	16	80	25	32
16	8	14x70	10	20	90	20	32
16	8	14x70	8	16	100	20	32
20	10	14x70	4	1111/14/32/2	140	32	44
16	8	14x70	10	20	80	20	32

